# **■** NetApp

## bridge events

ONTAP 9.14.1 EMS reference

NetApp February 12, 2024

This PDF was generated from https://docs.netapp.com/us-en/ontap-ems-9141/bridge-discovered-events.html on February 12, 2024. Always check docs.netapp.com for the latest.

## **Table of Contents**

bridge events	 	 	
bridge.discovered events	 	 	
bridge.duplicate events	 	 	
bridge.removed events	 	 	
bridge.sas events	 	 	
bridge.timestamp events	 	 	

## bridge events

## bridge.discovered events

## bridge.discovered

## Severity

**INFORMATIONAL** 

## **Description**

This message occurs when the system discovers an FC-to-SAS bridge.

#### **Corrective Action**

(None).

## **Syslog Message**

FC-to-SAS bridge %s [%s %s %s] S/N [%s] was discovered.

### **Parameters**

bridgeName (STRING): Name of the bridge.

**bridgeVendor** (STRING): Vendor name of the bridge. **bridgeModel** (STRING): Model name of the bridge.

**bridgeRevision** (STRING): Firmware revision of the bridge. **bridgeSerialNum** (STRING): Serial number of the bridge.

## bridge.duplicate events

## bridge.duplicate.ip.address

#### Severity

**ALERT** 

### **Description**

This message occurs when the system discovers an ATTO FibreBridge using the same IP address as some other device in the network.

#### **Corrective Action**

Using the IP and MAC addresses from the alert, attempt to locate the other device in the network, and change one of the IP addresses. If unsuccessful, contact NetApp support for assistance with this issue.

### Syslog Message

FC-to-SAS bridge %s [%s] %s %s %s.

#### **Parameters**

bridgeName (STRING): Name of the bridge that detected the duplicate IP address. bridgeSerialNum (STRING): Serial number of the bridge that detected the duplicate address. duplicateIPAddress (STRING): Duplicate IP address detection message from the bridge log. duplicateMAC (STRING): Duplicate MAC address detection message from the bridge log. addInfo (STRING): Additional information about the alert being generated, if available.

## bridge.duplicate.wwn

## Severity

**ALERT** 

## Description

This message occurs when the system discovers two FC-to-SAS bridges reporting the same WWN.

## **Corrective Action**

Contact NetApp support for assistance with this issue.

## **Syslog Message**

FC-to-SAS bridge %s [%s] and bridge %s [%s] are presenting a duplicate WWN [%s] %s.

### **Parameters**

bridgeName1 (STRING): Name of the first bridge.

**bridgeSerialNum1** (STRING): Serial number of the first bridge.

bridgeName2 (STRING): Name of the second bridge.

bridgeSerialNum2 (STRING): Serial number of the secondbridge.

bridgeWWN (STRING): World wide name of the bridges.

addInfo (STRING): Additional information about the alert being generated, if available.

## bridge.removed events

## bridge.removed

## Severity

**INFORMATIONAL** 

#### **Description**

This message occurs when an FC-to-SAS bridge is removed from the system.

### **Corrective Action**

(None).

## Syslog Message

FC-to-SAS bridge %s [%s %s %s] S/N [%s] was removed.

## **Parameters**

bridgeName (STRING): Name of the bridge.

**bridgeVendor** (STRING): Vendor name of the bridge. **bridgeModel** (STRING): Model name of the bridge.

**bridgeRevision** (STRING): Firmware revision of the bridge. **bridgeSerialNum** (STRING): Serial number of the bridge.

## bridge.sas events

## bridge.SAS.invalidTransition

## Severity

**ERROR** 

## **Description**

This message occurs when the SAS disk shelves behind an FC-to-SAS bridge are not cabled correctly, indicating an invalid SAS2 to SAS3 transition.

### **Corrective Action**

Follow the defined Fabric-attached or stretch MetroCluster cabling guide.

## Syslog Message

An invalid SAS2 to SAS3 transition exists on FC-to-SAS bridge %s S/N [%s]: %s

## **Parameters**

**bridgeName** (STRING): Name of the FC-to-SAS bridge. **bridgeSerialNum** (STRING): Serial number of the FC-to-SAS bridge. **bridgeError** (STRING): Error string from the FC-to-SAS bridge.

## bridge.timestamp events

## bridge.timestamp.noSync

## Severity

NOTICE

## **Description**

This message occurs when the max number of retries is exceeded when attempting to apply SCSI SET TIMESTAMP command on one or more attached FC-to-SAS bridges. A timestamp that is not in sync does not affect the functional operation of the bridge. The SET TIMESTAMP operation is only used to synchronize timestamps between ONTAP® and the bridge to assist with correlating log events.

### **Corrective Action**

A timestamp operation will always retry in 24 hours. If this notice persists, contact NetApp technical support.

## **Syslog Message**

ONTAP timestamp sync did not complete on FC-to-SAS bridge with S/N: %s WWN: %s.

## **Parameters**

**bridgeSerialNum** (STRING): Serial number of the bridge. **bridgeWWN** (STRING): World Wide Name of the bridge.

## Copyright information

Copyright © 2024 NetApp, Inc. All Rights Reserved. Printed in the U.S. No part of this document covered by copyright may be reproduced in any form or by any means—graphic, electronic, or mechanical, including photocopying, recording, taping, or storage in an electronic retrieval system—without prior written permission of the copyright owner.

Software derived from copyrighted NetApp material is subject to the following license and disclaimer:

THIS SOFTWARE IS PROVIDED BY NETAPP "AS IS" AND WITHOUT ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WHICH ARE HEREBY DISCLAIMED. IN NO EVENT SHALL NETAPP BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

NetApp reserves the right to change any products described herein at any time, and without notice. NetApp assumes no responsibility or liability arising from the use of products described herein, except as expressly agreed to in writing by NetApp. The use or purchase of this product does not convey a license under any patent rights, trademark rights, or any other intellectual property rights of NetApp.

The product described in this manual may be protected by one or more U.S. patents, foreign patents, or pending applications.

LIMITED RIGHTS LEGEND: Use, duplication, or disclosure by the government is subject to restrictions as set forth in subparagraph (b)(3) of the Rights in Technical Data -Noncommercial Items at DFARS 252.227-7013 (FEB 2014) and FAR 52.227-19 (DEC 2007).

Data contained herein pertains to a commercial product and/or commercial service (as defined in FAR 2.101) and is proprietary to NetApp, Inc. All NetApp technical data and computer software provided under this Agreement is commercial in nature and developed solely at private expense. The U.S. Government has a non-exclusive, non-transferrable, nonsublicensable, worldwide, limited irrevocable license to use the Data only in connection with and in support of the U.S. Government contract under which the Data was delivered. Except as provided herein, the Data may not be used, disclosed, reproduced, modified, performed, or displayed without the prior written approval of NetApp, Inc. United States Government license rights for the Department of Defense are limited to those rights identified in DFARS clause 252.227-7015(b) (FEB 2014).

#### **Trademark information**

NETAPP, the NETAPP logo, and the marks listed at <a href="http://www.netapp.com/TM">http://www.netapp.com/TM</a> are trademarks of NetApp, Inc. Other company and product names may be trademarks of their respective owners.